



## Technical Bulletin:

4 Post Sawmills - purchased since Oct.1, 2020

Some models have had the brass crank fitting wear prematurely.

This is due to it be overtightened at the manufacturer.

Fix: Before operating, check the round nut on the lift crank to make sure it is not over tightened. It should be just snug but not overly tight.

If you experience failure please contact your point of purchase for a replacement bushing.

